# Optimization of Micro-hardness of Al-SiC 6061 MMC Machined by Wire EDM with Taguchi method.

Rohit Sharma<sup>1</sup>, Vivek Aggarwal<sup>2</sup>, H. S. Payal<sup>3</sup>

*Mechanical Engineering*<sup>1,2,3</sup>, *IKGPTU, Kapurthala*<sup>1,2</sup>, *Himalayan School of Engineering and Technology*, *Dehradun*<sup>3</sup>

*Email: jaijairaghunath@rediff.com1*, agarwalz\_v@yahoo.com2, *payal\_hs@*yahoo.com<sup>3</sup>

Abstract-The usage of Al-SiC metal matrix composites is constantly increasing since the last many years due to their many unique properties such as light weight, high strength, high specific modulus, high fatigue strength, low density, and high hardness. However, because of their high hardness, their machining, that too within close tolerance limits, is often a big challenge. Wire EDM machining however offers a good method to machine these deemed difficult to machine alloys. This research work focuses on the wire EDM machining of Al-SiC 6061 metal matrix composite which is one of the most widely used metal matrix composites in the world today. Here, Taguchi approach has been applied to study the work-piece composition and machining parameters during the wire EDM machining and to maximize the micro-hardness of the surface obtained after the machining process. Different compositions of the Al-SiC MMC in terms of reinforcement percentages, along with six other operating parameters have been studied. L-16 Orthogonal Array (pronounced as ell-sixteen Orthogonal Array) has been used in the Taguchi approach for this purpose. Contributions of various factors to surface microhardness have been determined, amongst which, SiC percentage in the Al-SiC MMC had the greatest contribution. The conclusions and future scope of this study have also been discussed.

*Index Terms- Wire* Electric Discharge Machining; MMCs; Al-SiC; 6061; Composite; hardness; Orthogonal Arrays; Taguchi.

#### 1. INTRODUCTION

This work analyzes the various factors (also known as parameters) involved in the machining by wire-cut EDM machine. Conventional machine tools such as routers, saws, and lathes are often not suitable for machining composites and high strength alloys [1]. Wire EDM is hence one of the non-conventional methods used for machining such materials. It is one of the widely accepted advanced manufacturing processes used to machine complicated materials [2]. Elektra Supercut 734 was the wire EDM machine used for this work which uses a brass wire as cutting wire and deionized water as the dielectric. The dielectric is continuously kept in circulation through the machine and filtration unit in a closed circuit. Six factors of the machining process have been involved in this study, namely, the upper nozzle height, the wire feed rate, the (machining) current, the gap voltage, the (wire) tension, and the upper nozzle flow rate. Along with these six factors, the percentage of SiC particles in Al-SiC 6061 metal matrix composite has also been studied at two levels as specimen composition. Levels are defined as the setting of various factors in a factorial experiment. The Taguchi experimental design has been used for this purpose. It provides an efficient and systematic approach for determining the optimum machining parameters in the manufacturing processes [3].

The Al-SiC 6061 which has been used in this work is a Metal Matrix Composite (MMC). Metal matrix composites (MMCs) usually consist of a low-density metal, such as aluminum or magnesium, reinforced with particulates or fibers of a ceramic material, such as silicon carbide or graphite [4]. As a matter of fact, the most popular type of MMC is aluminum alloy reinforced with ceramic particles [5]. The two variations which have been studied in this work are that of 5% SiC and of 10% SiC reinforcements, respectively. Al-SiC 6061 MMC has the aluminum alloy of Al-6061 (called its matrix phase) with uniformly distributed SiC particles of 220 mesh size (called its reinforcement phase). An MMC having aluminum as its matrix phase is also sometimes called Aluminum Matrix Composite (AMC). These specimens had been prepared by stir casting process. Of various AMC manufacturing techniques, stir casting has the advantage of being the simplest, most flexible, and cheapest process of all [6].

An Orthogonal Array (OA) is a mathematical invention recorded by Jacques Hadamard, a French mathematician in as early as 1897 [7]. Orthogonal Array of 1-16 type had been found to be most appropriate for the study, hence had been employed. A factor is another name of a parameter in experiments. The most favorable levels of each of the seven factors

(six factors are the machining parameters of the machine and the seventh factor is that of the specimen composition; hence total seven factors) have been found out. Percentage contribution of each of these factors has also been worked out which describe that how dominantly each of these factors contributes to the final hardness of machined surfaces on this machine.

#### 2. MATERIALS AND METHODS

Composition analysis of the Al-6061 alloy was done by atomic emission spectrometry as per the ASTM E1251-2011 test method. Its results were tallied with statistically available data regarding Al-6061 alloy and the alloy was deemed authentic and hence acceptable for further research. The test results have been shown in Table 1 below,

Table 1. Spectrometry test results of Alumimium6061

Element	Cu	Mg	Si	Fe	Ni	Mn
Percenta	0.203	0.933	0.784	0.304	0.003	0.083
ge	0	0	0	0	2	6
Element	Zn	Pb	Sn	Ti	Cr	Al
Percenta	0.056	0.027	<	0.068	0.047	Remai
ge	1	0	0.010	9	2	ning

MMC was prepared out of this Al-6061 by stir casting process. Stir casting (SC) method involves the incorporation of reinforcements into liquid matrix melt through continuously stirring resulting into vortex mixing that enables the proper distribution of the reinforcements. The mixture of metal and reinforcement, called slurry, is allowed to solidify inside the pre-fabricated mold cavity [8]. SiC powder of 220 mesh size had been taken as reinforcement phase and preheated to a temperature of 3500° C. SiC is the best strengthening reinforcement since it is having a higher value of Vickers (hardness) [9]. This temperature was maintained for about half an hour so as to remove moisture and volatile matter. The carefully weighed Al-SiC alloy was heated in a vertical muffle furnace to about 850° C, and the preheated SiC particles were then added to them. 1% by weight magnesium ribbon strip was also put in the crucible so as to increase the bonding of SiC particles with the molten Al-SiC. If the bonding between the two is weak, which can occur due to wettability issues or lack of interaction in-between, the final composite will have poor mechanical properties [10]. A stirrer of graphite was left to rotate in the molten slurry for some time. After removal of slag, the metal was poured into two specially prepared cylinder molds, one with 5% SiC composition and another of the 10% SiC composition, respectively.

Taguchi design of experiments had been planned in order to investigate the effect of cutting parameters on these two specimens. It is an efficient test strategy which possesses many advantages because of its balanced arrangement. When each experimental run was decided in terms of various parameters and their levels, the machining cuts were performed on specimens by wire EDM machining so as to investigate the performance of machining of this MMC material on wire EDM machine. Wire electrical discharge machining is a particular thermal noncontact technique of machining [11]. It is a spark erosion process used to produce complex two and three-dimensional shapes through electrically conductive work-pieces [12]. It removes the material by erosion procedure. Series of constantly repeating electrical discharges emerge between the tool and the work-piece in a dielectric fluid and remove the material [13]. It is hence deemed suitable for machining of exceptionally hard materials with good electrical conductivity, especially the MMCs.

The machining cuts which were performed on the specimens were 48 in number. These were carried out in accordance with the conditions described by the l-16 orthogonal array. Each of these cuts was 14 mm deep, and all these cuts were placed mutually at an axial distance of 2.5 mm. The model is shown in



Figure 1, and the actual cut out pieces have been shown in Figure 2.

Fig. 1. The model showing the red colored surface being machined on a specimen. This is one of the surfaces whose hardness values are to be used in further analysis.

Fig. 2. The cut out semi-circular disc-shaped specimens whose surfaces had to be analyzed for their microhardness values and considered in the Taguchi method.

The microhardness values of these tests had been performed on the Rockwell hardness testing machine with diamond tip indenter, as shown in Figure 3.

Fig. 3. Rockwell microhardness testing machine (details). The yellow rectangle indicates the turret on which the specimen was needed to be placed, the green rectangle shows the hand wheel for application of minor load on the specimen, and the red rectangle



shows the lever for the release of major load on the surface of specimen by the indenter.

In order to conduct the microhardness tests of the pieces obtained from the specimens after wire EDM machining, according to tables, the diamond tip indenter for a load of 60 kg was selected. This indenter was mounted on the turret upside down over the test table. After a specific semi-circular disc-shaped specimen was placed with its test surface



towards the top on the test table whose position has been shown by a yellow circle, the hand wheel beneath it was rotated so as to raise it to touch the indenter.

#### 3. RESULTS AND DISCUSSION

#### 3.1. Design of experiments

For the sake of accuracy, five readings had been taken on the surface of each specimen at various random places, and their averages had been considered in the study. These readings have been shown in Table 2 below.

Table 2. Microhardnessvaluesofspecimens( numbered 1 to 48)

No. of specimen	place ( HRA ) st Microhardness at 1	place ( HRA ) ndMicrohardness at 2	place ( HRA ) rdMicrohardness at 3	place ( HRA ) th Microhardness at 4	place ( HRA ) th Microhardness at 5	Average micro hardness (HR4)
1	95	67	69	78	67	75.2
2	86	76	84	79	62	77.4
3	82	85	83	86	87	84.6
4	90	75	90	82	82	83.8
5	81	84	75	94	82	83.2
6	86	78	88	86	82	84.0
7	54	69	73	74	67	67.4
8	79	70	82	79	77	77.4
9	76	60	73	83	67	71.8
10	76	78	68	85	76	76.6
11	85	85	90	90	88	87.6
12	86	88	86	87	78	85.0
13	86	86	88	85	88	86.6
14	92	89	95	89	84	89.8
15	80	84	83	86	87	84.0
16	58	80	72	78	78	73.2
17	60	75	62	82	83	72.4
18	70	48	83	30	77	61.6
19	80	91	89	89	87	87.2
20	90	91	92	94	89	91.2
21	90	91	90	90	88	89.8
22	87	90	90	90	85	88.4

23 $86$ $82$ $94$ $95$ $70$ $85.4$ $24$ $83$ $87$ $88$ $84$ $80$ $84.4$ $25$ $79$ $86$ $92$ $82$ $82$ $84.2$ $26$ $92$ $89$ $81$ $81$ $77$ $84.0$ $27$ $89$ $84$ $84$ $91$ $89$ $87.4$ $28$ $91$ $92$ $90$ $89$ $87$ $89.8$ $29$ $88$ $89$ $91$ $92$ $82$ $88.4$ $30$ $88$ $87$ $86$ $88$ $84$ $86.6$ $31$ $80$ $75$ $70$ $70$ $90$ $77.0$ $32$ $94$ $87$ $92$ $87$ $79$ $87.8$ $33$ $92$ $87$ $84$ $91$ $64$ $83.6$ $34$ $90$ $91$ $90$ $92$ $90$ $90.6$ $35$ $88$ $87$ $90$ $87$ $89$ $88.2$ $36$ $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ </th <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th>							
24 $83$ $87$ $88$ $84$ $80$ $84.4$ $25$ $79$ $86$ $92$ $82$ $82$ $84.2$ $26$ $92$ $89$ $81$ $81$ $77$ $84.0$ $27$ $89$ $84$ $84$ $91$ $89$ $87.4$ $28$ $91$ $92$ $90$ $89$ $87$ $89.8$ $29$ $88$ $89$ $91$ $92$ $82$ $88.4$ $30$ $88$ $87$ $86$ $88$ $84$ $86.6$ $31$ $80$ $75$ $70$ $70$ $90$ $77.0$ $32$ $94$ $87$ $92$ $87$ $79$ $87.8$ $33$ $92$ $87$ $84$ $91$ $64$ $83.6$ $34$ $90$ $91$ $90$ $92$ $90$ $90.6$ $35$ $88$ $87$ $90$ $87$ $89$ $88.2$ $36$ $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $89$ $91$ $93$ $91.8$ $38$ $93$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ </td <td>23</td> <td>86</td> <td>82</td> <td>94</td> <td>95</td> <td>70</td> <td>85.4</td>	23	86	82	94	95	70	85.4
25 $79$ $86$ $92$ $82$ $82$ $84$ $28$ $91$ $89$ $81.$ $27$ $89$ $84$ $84$ $91$ $89$ $87.4$ $28$ $91$ $92$ $90$ $89$ $87$ $89.8$ $29$ $88$ $89$ $91$ $92$ $82$ $88.4$ $30$ $88$ $87$ $86$ $88$ $84$ $86.6$ $31$ $80$ $75$ $70$ $70$ $90$ $77.0$ $32$ $94$ $87$ $92$ $87$ $79$ $87.8$ $33$ $92$ $87$ $84$ $91$ $64$ $83.6$ $34$ $90$ $91$ $90$ $92$ $90$ $90.6$ $35$ $88$ $87$ $90$ $87$ $89$ $88.2$ $36$ $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ $44$ $89$ $87$ $93$ $92$ $91$ $90.4$ $45$ $89$ $91$ $91$ $92$ $91$ $90.8$ $46$ $92$ $91$	24	83	87	88	84	80	84.4
26 $92$ $89$ $81$ $81$ $77$ $84.0$ $27$ $89$ $84$ $84$ $91$ $89$ $87.4$ $28$ $91$ $92$ $90$ $89$ $87$ $89.8$ $29$ $88$ $89$ $91$ $92$ $82$ $88.4$ $30$ $88$ $87$ $86$ $88$ $84$ $86.6$ $31$ $80$ $75$ $70$ $70$ $90$ $77.0$ $32$ $94$ $87$ $92$ $87$ $79$ $87.8$ $33$ $92$ $87$ $84$ $91$ $64$ $83.6$ $34$ $90$ $91$ $90$ $92$ $90$ $90.6$ $35$ $88$ $87$ $90$ $87$ $89$ $88.2$ $36$ $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $89$ $91$ $93$ $91.8$ $38$ $93$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ $44$ $89$ $87$ $93$ $92$ $91$ $90.4$ $45$ $89$ $91$ $91$ $92$ $91$ $90.8$ </td <td>25</td> <td>79</td> <td>86</td> <td>92</td> <td>82</td> <td>82</td> <td>84.2</td>	25	79	86	92	82	82	84.2
27 $89$ $84$ $84$ $91$ $89$ $87.4$ $28$ $91$ $92$ $90$ $89$ $87$ $89.8$ $29$ $88$ $89$ $91$ $92$ $82$ $88.4$ $30$ $88$ $87$ $86$ $88$ $84$ $86.6$ $31$ $80$ $75$ $70$ $70$ $90$ $77.0$ $32$ $94$ $87$ $92$ $87$ $79$ $87.8$ $33$ $92$ $87$ $84$ $91$ $64$ $83.6$ $34$ $90$ $91$ $90$ $92$ $90$ $90.6$ $35$ $88$ $87$ $90$ $87$ $89$ $88.2$ $36$ $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $89$ $91$ $93$ $91.8$ $38$ $93$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ $44$ $89$ $87$ $93$ $92$ $91$ $90.4$ $45$ $89$ $91$ $91$ $92$ $91$ $90.8$ $46$ $92$ $91$ $90$ $84$ $91$ $89.6$ </td <td>26</td> <td>92</td> <td>89</td> <td>81</td> <td>81</td> <td>77</td> <td>84.0</td>	26	92	89	81	81	77	84.0
28 $91$ $92$ $90$ $89$ $87$ $89.8$ $29$ $88$ $89$ $91$ $92$ $82$ $88.4$ $30$ $88$ $87$ $86$ $88$ $84$ $86.6$ $31$ $80$ $75$ $70$ $70$ $90$ $77.0$ $32$ $94$ $87$ $92$ $87$ $79$ $87.8$ $33$ $92$ $87$ $84$ $91$ $64$ $83.6$ $34$ $90$ $91$ $90$ $92$ $90$ $90.6$ $35$ $88$ $87$ $90$ $87$ $89$ $88.2$ $36$ $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $89$ $91$ $93$ $91.8$ $38$ $93$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ $44$ $89$ $87$ $93$ $92$ $91$ $90.4$ $45$ $89$ $91$ $91$ $92$ $91$ $90.8$ $46$ $92$ $91$ $90$ $84$ $91$ $89.6$ $47$ $92$ $95$ $95$ $96$ $84$ $92.4$ </td <td>27</td> <td>89</td> <td>84</td> <td>84</td> <td>91</td> <td>89</td> <td>87.4</td>	27	89	84	84	91	89	87.4
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	28	91	92	90	89	87	89.8
30888786888486.6 $31$ 807570709077.0 $32$ 948792877987.8 $33$ 928784916483.6 $34$ 909190929090.6 $35$ 888790878988.2 $36$ 898891948589.4 $37$ 939389919391.8 $38$ 939392909592.6 $39$ 898974948285.6 $40$ 828792868386.0 $41$ 919193947488.6 $42$ 889492738987.2 $43$ 858889878687.0 $44$ 898793929190.4 $45$ 899191929190.8 $46$ 929190849189.6 $47$ 929595968492.4 $48$ 528785968581.0	29	88	89	91	92	82	88.4
31 $80$ $75$ $70$ $70$ $90$ $77.0$ $32$ $94$ $87$ $92$ $87$ $79$ $87.8$ $33$ $92$ $87$ $84$ $91$ $64$ $83.6$ $34$ $90$ $91$ $90$ $92$ $90$ $90.6$ $35$ $88$ $87$ $90$ $87$ $89$ $88.2$ $36$ $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $89$ $91$ $93$ $91.8$ $38$ $93$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ $44$ $89$ $87$ $93$ $92$ $91$ $90.4$ $45$ $89$ $91$ $91$ $92$ $91$ $90.8$ $46$ $92$ $91$ $90$ $84$ $91$ $89.6$ $47$ $92$ $95$ $95$ $96$ $84$ $92.4$ $48$ $52$ $87$ $85$ $96$ $85$ $81.0$	30	88	87	86	88	84	86.6
32 $94$ $87$ $92$ $87$ $79$ $87.8$ $33$ $92$ $87$ $84$ $91$ $64$ $83.6$ $34$ $90$ $91$ $90$ $92$ $90$ $90.6$ $35$ $88$ $87$ $90$ $87$ $89$ $88.2$ $36$ $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $89$ $91$ $93$ $91.8$ $38$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ $44$ $89$ $87$ $93$ $92$ $91$ $90.4$ $45$ $89$ $91$ $91$ $92$ $91$ $90.8$ $46$ $92$ $91$ $90$ $84$ $91$ $89.6$ $47$ $92$ $95$ $95$ $96$ $84$ $92.4$ $48$ $52$ $87$ $85$ $96$ $85$ $81.0$	31	80	75	70	70	90	77.0
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	32	94	87	92	87	79	87.8
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	33	92	87	84	91	64	83.6
35 $88$ $87$ $90$ $87$ $89$ $88.2$ $36$ $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $89$ $91$ $93$ $91.8$ $38$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ $44$ $89$ $87$ $93$ $92$ $91$ $90.4$ $45$ $89$ $91$ $91$ $92$ $91$ $90.8$ $46$ $92$ $91$ $90$ $84$ $91$ $89.6$ $47$ $92$ $95$ $95$ $96$ $84$ $92.4$ $48$ $52$ $87$ $85$ $96$ $85$ $81.0$	34	90	91	90	92	90	90.6
36 $89$ $88$ $91$ $94$ $85$ $89.4$ $37$ $93$ $93$ $89$ $91$ $93$ $91.8$ $38$ $93$ $93$ $92$ $90$ $95$ $92.6$ $39$ $89$ $89$ $74$ $94$ $82$ $85.6$ $40$ $82$ $87$ $92$ $86$ $83$ $86.0$ $41$ $91$ $91$ $93$ $94$ $74$ $88.6$ $42$ $88$ $94$ $92$ $73$ $89$ $87.2$ $43$ $85$ $88$ $89$ $87$ $86$ $87.0$ $44$ $89$ $87$ $93$ $92$ $91$ $90.4$ $45$ $89$ $91$ $91$ $92$ $91$ $90.8$ $46$ $92$ $91$ $90$ $84$ $91$ $89.6$ $47$ $92$ $95$ $95$ $96$ $84$ $92.4$ $48$ $52$ $87$ $85$ $96$ $85$ $81.0$	35	88	87	90	87	89	88.2
37939389919391.838939392909592.639898974948285.640828792868386.041919193947488.642889492738987.243858889878687.044898793929190.445899191929190.846929190849189.647929595968492.448528785968581.0	36	89	88	91	94	85	89.4
389392909592.639898974948285.640828792868386.041919193947488.642889492738987.243858889878687.044898793929190.445899191929190.846929190849189.647929595968492.448528785968581.0	37	93	93	89	91	93	91.8
39     89     89     74     94     82     85.6       40     82     87     92     86     83     86.0       41     91     91     93     94     74     88.6       42     88     94     92     73     89     87.2       43     85     88     89     87     86     87.0       44     89     87     93     92     91     90.4       45     89     91     91     92     91     90.8       46     92     91     90     84     91     89.6       47     92     95     95     96     84     92.4       48     52     87     85     96     85     81.0	38	93	93	92	90	95	92.6
40828792868386.041919193947488.642889492738987.243858889878687.044898793929190.445899191929190.846929190849189.647929595968492.448528785968581.0	39	89	89	74	94	82	85.6
41919193947488.642889492738987.243858889878687.044898793929190.445899191929190.846929190849189.647929595968492.448528785968581.0	40	82	87	92	86	83	86.0
42889492738987.243858889878687.044898793929190.445899191929190.846929190849189.647929595968492.448528785968581.0	41	91	91	93	94	74	88.6
43858889878687.044898793929190.445899191929190.846929190849189.647929595968492.448528785968581.0	42	88	94	92	73	89	87.2
44898793929190.445899191929190.846929190849189.647929595968492.448528785968581.0	43	85	88	89	87	86	87.0
45899191929190.846929190849189.647929595968492.448528785968581.0	44	89	87	93	92	91	90.4
46929190849189.647929595968492.448528785968581.0	45	89	91	91	92	91	90.8
47     92     95     95     96     84     92.4       48     52     87     85     96     85     81.0	46	92	91	90	84	91	89.6
48 52 87 85 96 85 81.0	47	92	95	95	96	84	92.4
	48	52	87	85	96	85	81.0

The Taguchi l-16 orthogonal array used in this work directs to use 16 experimental trials. For the sake of accuracy, each of these tests had been performed 3 times, because of which, the total number of tests had come out to be 48 (16x3). This was done in accordance with the concept of repetition. These are the 16 settings which have been directed by the l-16 orthogonal array in accordance to which these 48 tests had been performed. Table 3 shows these 16 values which we next used in the orthogonal array.

Table 3. Average micro hardness obtained during machining at each setting of Orthogonal Array (numbered 1 to 16)

S. No.	Specimen 1 to 16 ( HRA)	Specimen 17 to 32 ( HRA)	Specimen 33 to 48 ( HRA)	) (HRA) Average ( <i>I to 16</i>
1	75.2	72.4	83.6	77.1
2	77.4	61.6	90.6	76.5
3	84.6	87.2	88.2	86.7
4	83.8	91.2	89.4	88.1
5	83.2	89.8	91.8	88.3
6	84	88.4	92.6	88.3
7	67.4	85.4	85.6	79.5
8	77.4	84.4	86	82.6
9	71.8	84.2	88.6	81.5
10	76.6	84	87.2	82.6
11	87.6	87.4	87	87.3
12	85	89.8	90.4	88.4
13	86.6	88.4	90.8	88.6
14	89.8	86.6	89.6	88.7
15	84	77	92.4	84.5
16	73.2	87.8	81	80.7

As per the standard method of Taguchi analysis of orthogonal arrays, these 16 values had been placed on the right side of the 1-16 orthogonal array, as shown in Table 4 below.

Table 4. Orthogonal Array 1 16 for microhardness

|--|

International Journal of Research in Advent Technology,	Vol.6, No.12,	December	2018
E-ISSN: 2321-9637			
4 ·1 1 1 1 · , · · ,			

Available online at www.ijrat.org

	Level 3				1.00A	A 89	1100 g	2.0 l.p.m.	microhardness
	Level 2	10 % SiC	50 mm	5 m/min	0.75 A	64 V	1000 g	1.5 l.p.m.	A) Average
	Level 1	5 % SiC	40 mm	3 m/min	0.50 A	A 09	900 g	1.0 l.p.m.	(HR
	Factors	Work-piece	Upper nozzle height	Wire feed rate	Current	Gap voltage	Tension	Upper nozzle flow rate	
	Exp. trial no.	Factor A	Factor B	Factor C	Factor D	Factor E	Factor F	Factor G	
	1	1	1	1	1	1	1	1	77.1
	2	1	2	2	1	2	2	2	76.5
	3	2	1	2	1	3	3	3	86.7
	4	2	2	1	1	4	4	4	88.1
	3	2	2	1	2	1	2	1	88.3
	0	2	1	2	2	2	1	4	88.J
	/ 0	1	4	4	2	3	4	4	19.3
	0	1	2	2	2	4	2	3	02.0
	י 10	1	2 1	2 1	3	2	3 1	4	01.3 82.6
	10	2	2	1	3	4	4	2	873
	12	2	2	2	3	<u>з</u> Л	2	2	88 /
	12	2	1	2	4	1	4	2	88.6
	14	2	2	1	4	2	3	1	88 7
	15	1	1	1	4	3	2	4	84 5
	16	1	2	2	4	4	1	3	80.7
IJ	10	-		<i>#</i>					1 00.1

#### 3.2. Mathematical analysis

3.2.1. Calculations for Average Effects of microhardness

Based on Table 4 given above, next, the Average Effects of microhardness were calculated. The

calculations have been shown below. Average Effects of A at levels 1 and 2,  $A_1 = (77.1 + 76.5 + 79.5 + 82.5 + 81.5 +$ 82.6 + 84.5 + 80.7) / 8 = 80.625,  $A_2 = (86.7 + 88.1 + 88.3 + 88.3 + 87.3 +$ 88.4 + 88.6 + 88.7 ) / 8 = 88.050. Average Effects of B at levels 1 and 2,  $B_1 = (77.1 + 86.7 + 88.3 + 82.6 + 82.6 +$ 88.4 + 88.6 + 84.5) / 8 = 84.850,  $B_2 = (76.5 + 88.1 + 88.3 + 79.5 + 81.5 +$ 87.3 + 88.7 + 80.7) / 8 = 83.825. Average Effects of C at levels 1 and 2,  $C_1 = (77.1 + 88.1 + 88.3 + 82.6 + 82.6 +$ 87.3 + 88.7 + 84.5) / 8 = 84.900,  $C_2 = (76.5 + 86.7 + 88.3 + 79.5 + 81.5 +$ 88.4 + 88.6 + 80.7 ) / 8 = 84.338. Average Effects of D at levels 1, 2, 3, and 4,  $D_1 = (77.1 + 76.5 + 86.7 + 88.1) / 4 =$ 82.100,  $D_2 = (88.3 + 88.3 + 79.5 + 82.6) / 4 =$ 84.675.  $D_3 = (81.5 + 82.6 + 87.3 + 88.4) / 4 =$ 84.950,  $D_4 = (88.6 + 88.7 + 84.5 + 80.7) / 4 =$ 85.625. Average Effects of E at levels 1, 2, 3, and 4,  $E_1 = (77.1 + 88.3 + 81.5 + 88.6) / 4 =$ 83.875,  $E_2 = (76.5 + 88.3 + 82.6 + 88.7) / 4 =$ 84.025,  $E_3 = (86.7 + 79.5 + 87.3 + 84.5) / 4 =$ 84.500,  $E_4 = (88.1 + 82.6 + 88.4 + 80.7) / 4 =$ 84.950. Average Effects of F at levels 1, 2, 3, and 4,  $F_1 = (77.1 + 88.3 + 87.3 + 80.7) / 4 =$ 83.350,  $F_2 = (76.5 + 88.3 + 88.4 + 84.5) / 4 =$ 84.425,  $F_3 = (86.7 + 82.6 + 81.5 + 88.7) / 4 =$ 84.875,  $F_4 = (88.1 + 79.5 + 82.6 + 88.6) / 4 =$ 84.700. Average Effects of G at levels 1, 2, 3, and 4,  $G_1 = (77.1 + 88.3 + 88.4 + 88.7) / 4 =$ 85.625,  $G_2 = (76.5 + 88.3 + 87.3 + 88.6) / 4 =$ 85.175,  $G_3 = (86.7 + 82.6 + 82.6 + 80.7) / 4 =$ 83.150,

 $G_4 = (88.1 + 79.5 + 81.5 + 84.5) / 4 =$ 83.400. These Average Effects can be summarized, as

shown in Table 5.

Table 5. The Average Effects

2

Factor	Factor name	Level I, LI	Level 2, L2	Level 3, L3	Level 4, L4
А	Work- piece	80.625	88.050	-	-
В	Upper nozzle height	84.850	83.825	-	-
С	Wire feed rate	84.900	84.338	-	-
D	Current	82.100	84.675	84.950	85.625
Е	Gap voltage	83.875	84.025	84.500	84.950
F	Tension	83.350	84.425	84.875	84.700
G	Upper nozzle flow rate	85.625	85.175	83.150	83.400

3.3.2. Calculations for sum of squares of factors and their percentage contribution

Based on Table 5 given above, next, the sum of squares of each factor is calculated. The relation used here is shown in Eq. (1),

SS = 
$$\frac{\sum x - x_m^2}{n-1}$$

(1)

Here,  $x_m$  is the Mean of Levels which have been calculated in Table 6, n is the degrees of freedom, taken as one for all two-level factors and three for all four-level factors, and other terms have their usual notations.

Furthermore, these sum of squares have been used to calculate the percent contribution of various factors for microhardness. This has been shown in Table 6 to Table 9 below.

Table 6. MeansofLevels(tocalculatePercentContribution for microhardness)

Factor	Level 1, L1	Level 2, L2	Level 3, L3	Level 4, L4	m Mean of Levels (x
А	80.625	88.050	-	-	84.34
В	84.850	83.825	-	-	84.338

С	84.900	83.775	-	-	84.338
D	82.100	84.675	84.950	85.625	84.338
Е	83.875	84.025	84.500	84.950	84.338
F	83.350	84.425	84.875	84.700	84.338
G	85.625	85.175	83.150	83.400	84.338

Table 7. Calculations of Percent Contribution for microhardness

Factor	Ш - х т	L2 - x m	L3 - x m	L4 - X M
Α	-3.713	3.712	-	-
В	0.512	-0.513	-	-
С	0.562	-0.563	-	-
D	-2.238	0.337	0.612	1.287
Е	-0.463	-0.313	0.162	0.612
F	-0.988	0.087	0.537	0.362
G	1.287	0.837	-1.188	-0.938

Table 8.Sum of squares (to calculate PercentContribution for microhardness)

actor	(L1-x m	(L2-x m	(L3-x m	(L4-x m	R
Ŧ	<b>7</b> )	<b>7</b> •	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	5 )	
А	13.78	13.77	-	-	27.5
	6	9			65
В	0.262	0.263	-	-	0.52
					5
С	0.316	0.317	-	-	0.63
					3
D	5.009	0.114	0.375	1.656	7.15
					3
Е	0.214	0.098	0.026	0.375	0.71
					3
F	0.976	0.008	0.288	0.131	1.40
					3
G	1.656	0.701	1.411	0.880	4.64



Table 9. Percent Contribution for microhardness

Factor	ы	(n) .F. D	Sum of squares
А	27.565	1	27.565
В	0.525	1	0.525
С	0.633	1	0.633
D	7.153	3	2.384
Е	0.713	3	0.238
F	1.403	3	0.468
G	4.648	3	1.549

The percent contribution of various factors has been shown graphically in Figure 4.

Fig. 4. A bar chart showing the percent contribution of various factors in the wire EDM machining of Al-SiC 6061 alloy.

# 3.3. Determination of factor levels for achieving maximum microhardness values

As per the Taguchi technique, the main effects of microhardness need to be plotted graphically for each factor, one by one. This is done by plotting the Average Effects of that factor on two-dimensional graph, as shown in Figure 5.

3.3.1.

In the context of the SiC percentage of both the specimens, the plots of the main effects have been



shown below.

The Average Effects, depicted in Table 5 have been plotted along the y-axis and the levels of factors have been plotted along the x-axis in Figure 5.

Fig. 5. Graphical representation of the main effects of factor A (both specimens' SiC percentage). Y-axis has Average Effects in units of HRA and X-axis has 5% SiC composition specimen as A1 and 10% SiC composition as A2.

The microhardness needs to be maximized. Hence, on the visual examination of Figure 5 above, we see that the factor level that shall result in a higher value of microhardness is A2.

#### 3.3.2.

In the context of the upper nozzle height of the wire EDM machine, the plots of the main effects have been shown below.



## International Journal of Research in Advent Technology, Vol.6, No.12, December 2018 E-ISSN: 2321-9637

Available online at www.ijrat.org

The Average Effects, depicted in Table 5 have been plotted along the y-axis and the levels of factors been plotted along the x-axis in Figure 6.

Fig. 6. Graphical representation of the main effects of factor B (upper nozzle height). Y-axis has Average Effects in units of HRA and X-axis has 40 mm as B1 and 50 mm as B2.

We see that the factor level that shall result in a higher value of microhardness is B1.

3.3.3.

In the context of the wire feed rate, the plots of the main effects have been shown below.

The Average Effects, depicted in Table 5 have been



plotted and the levels of factors have been plotted along the x-axis in Figure 7.

Fig. 7. Graphical representation of the main effects of factor C (wire feed rate). Y-axis has Average Effects in units of HRA and X-axis has wire feed rate as level C1 and level C2 in units of m/min.

The microhardness needs to be maximized. Hence, on the visual examination of Figure 7 above, we see that the factor level that shall result in a higher value of microhardness is C1.



3.3.4.

In the context of the (machining) current used in the Wire EDM machine, the plots of the main effects have been shown below.

The Average Effects, depicted in Table 5 have been plotted along the y-axis and the levels of factors have been plotted along the x-axis in Figure 8.

Fig. 8. Graphical representation of the main effects of factor D (machining current). Y-axis has Average Effects in units of HRA and X-axis has machining current as a factor at levels D1, D2, D3, and D4 in units of amperes.

The microhardness needs to be maximized. Hence, on the visual examination of Figure 8 above, we see that the factor level that shall result in a higher value of microhardness is D3.

3.3.5.

In the context of the gap voltage between the electrode wire of the Wire EDM machine and the workpiece to



be machined, the plots of the main effects have been shown below.

The Average Effects, depicted in Table 5 have been plotted along the y-axis and the levels of factors have been plotted along the x-axis in Figure 9.



Fig. 9. Graphical representation of the main effects of factor E (gap voltage). Y-axis has Average Effects in units of HRA and X-axis has gap voltage as a factor at levels E1, E2, E3, and E4 in units of volts.

The microhardness needs to be maximized. Hence, we see that the factor level that shall result in a higher value of microhardness is E4.

#### 3.3.6.

In context of the wire tension, the Average Effects have been plotted along the y-axis and the levels of factors along the x-axis in Figure 10.



Fig. 10. Graphical representation of the main effects of factor F (wire tension ). Y-axis has Average Effects in units of HRA and X-axis has (wire) tension as a factor at levels F1, F2, F3, and F4 in units of grams.

The microhardness needs to be maximized. Hence, on the visual examination of Figure 10 above, we see that the factor level that shall result in a higher value of microhardness is F3.

#### 3.3.7.

In the context of the upper nozzle flow rate, the plots of the main effects have been shown below.

The Average Effects, depicted in Table 5 have been plotted along the y-axis and the levels of factors have been plotted along the x-axis in Figure 11.



Fig. 11. Graphical representation of the main effects of factor G (upper nozzle flow rate). Y-axis has Average Effects in units of HRA and X-axis has upper nozzle flow rate as a factor at levels G1, G2, G3, and G4 in units of l.p.m.

The microhardness needs to be maximized. Hence, on the visual examination of Figure 11 above, we see that the factor level that shall result in a higher value of microhardness is G1.

From the visual examination of figures above, we see that the levels of various factors that shall result in a high value of microhardness correspond to A2 B1C1 D3 E4 F3 G1.

The levels of various factors that shall result in a high value of microhardness can be shown in tabular form, as in Table 10.

Factor Name	Factor Description	Factor Levels	Factor Values	
A	Work-piece	A <sub>2</sub>	SiC 10 %	
В	Upper nozzle height	<b>B</b> 1	40 mm	
С	Wire feed rate	<b>C</b> <sub>1</sub>	3 m/min	
D	Current	<b>D</b> <sub>3</sub>	1 A	
Е	Gap voltage	E4	72 V	
F	Tension	F3	1100 g	
G	Upper nozzle flow rate	G <sub>1</sub>	1 l.p.m.	

Table 10. Levels of factors for maximization of microhardness

It is deemed that the above-mentioned levels of the given factors were to result in a higher value of microhardness.

3.4. Projection performance of optimal (microhardness) According to the usual notations, here, Number of observations, N = 16Total of all observations, T According to the usual notations, here, Total number of observations, N = 16Sum total of all observations, T = 77.1 + 76.5 + 86.7 + 88.1 + 88.3 + 88.3 +79.5 + 82.6 + 81.5 + 82.6 + 87.3 + 88.4 +88.6 + 88.7 + 84.5 + 80.7 = 1349.4.Optimal performance,  $Y_{optimal} = T/N + (A_2 - T/N) + (B_{1-}T/N) +$  $(C_{1-}T/N) + (D_3 - T/N) + (E_4 - T/N) + (F_3)$  $_{-}$  T/N ) + ( G<sub>1</sub> - T/N ), = 84.338 + (88.050 - 84.338) + (84.850 -84.338 + (84.900 - 84.338) + (84.950 - 84.338)84.338) +(84.950 - 84.338) + (84.875 - 84.338) +(85.625 - 84.338),= 84.338 + (3.712) + (0.512) + (0.562) +(0.612) + (0.612) + (0.537) + (1.287), = 92.172 HRA.

#### 4. CONFIRMATION TESTS

It is recommended that the projected optimal performance should be checked by running confirmatory tests. After the aforesaid calculations were made, confirmatory experiments were carried out as per the parameter settings of Table 10.

A total of three tests were performed, and hence, three specimens were prepared. All these specimens were prepared from the SiC 10 % composition casting which corresponds to A2. In order to prepare these specimens, the SiC 10 % composition casting was mounted on the Wire EDM machine. The various parameters were set according to the Table 10, after which, the machining cuts were made on the casting. This resulted in three specimens which had been cut on the parameter settings recommended for obtaining maximum microhardness value. Similar to the earlier cut specimens during the test, the microhardness values were measured on all these three specimens at five random points on their surfaces on the same microhardness testing machine, and the average of these five points was taken. Then the average microhardness values of these three specimens were taken. The readings have been shown in Table 11 below.

Table 11. Confirmation tests for microhardness

oecimen number	I Micro-hardness   d2 (HRA)   3 (HRA)				Average (HRA)	)verall average (HRA)	
$\mathbf{S}\mathbf{p}$	S	50	rı	th	t t		0
	ding	ding	ing	ing	ting		
	rea	rea	read	read	read		
С	90	89	91	90	90	90.000	91.13
1							
С	90	91	93	90	90	90.800	
2							
С	92	91	93	94	93	92.600	
3							

These results have been shown graphically in Figure 12 on being compared with their accuracy of predicted values.

The value of microhardness which had been calculated by projection of optimal performance are 101.143% of the actual values which are quite satisfactory.

Fig. 12. Comparison of predicted and actual values of microhardness obtained after the confirmation tests.

#### 5. CONCLUSIONS AND FUTURE SCOPE

It has been found out in this study that during the machining of Al-SiC MMC material carried out on a Wire EDM machine, the factor which most significantly affects the microhardness of the



specimens is the work-piece composition, that is, the percentage of reinforcement phase, SiC particles in this case. Clearly, a 10% SiC composition aluminum MMC gives greater hardness values than 5% SiC composition one. Similar had been the results by Karthick et al. in an earlier study regarding magnesium based MMCs [14]. After that, the various factors which affect the microhardness values of surface machined out by Wire EDM machine in the decreasing order of significance are (machining) current, upper nozzle flow rate, wire feed rate, upper nozzle height, wire tension, and gap voltage, respectively.

It was seen that with the design of experiments being done in accordance with the Taguchi technique, we were able to achieve quite high values of surface microhardness. Wire EDM is a non-conventional machining process employed for the machining of difficult to machine materials which are too hard to be machined by conventional processes.

Hardness is an important property which should be preserved and enhanced during a machining process. This paper puts forward an experimental technique by which an optimal combination of parameters may be determined which results in higher values of surface microhardness. This is liable to result in higher operating lives of products obtained after machining, for example, the extrusion dies which are obtained by the operation of taper cutting carried on wire EDM machines. It also lays down a possibility that the microhardness values can be planned well in advance of the surfaces which shall be obtained during wire EDM machining. For example, in order to obtain less brittle surface in some specific requirement, lower values of microhardness could also be achieved by this method.

#### REFERENCES

- [1] H. Liu. "7M" Advantages of Abrasive Waterjet for Machining Advanced Materials". J. Manuf. Mater. Process, volume 1, page 11, 2017.
- [2] P. Vundavilli and J. Kumar, C. Priyatham. "Parameter optimization of wire electric discharge machining process using GA and PSO". In IEEE-International Conference On Advances In Engineering, Science And Management (ICAESM -2012), Nagapattinam, Tamil Nadu, pages 180-185, 2012.
- [3] Y. Ahmed, H. Youssef, and H. Hofy. "Prediction and Optimization of Drilling Parameters in Drilling of AISI 304 and AISI 2205 Steels with PVD Monolayer and Multilayer Coated Drills". J. Manuf. Mater. Process., volume 2(1), page 16, 2018.
- [4] "Advanced Materials by design". Washington DC, US Government Printing Office, chapter 1, page 9, 1988.
- [5] N. Muthukrishnan and J. Davim. "Optimization of Machining Parameters of Al/SiC-MMC with ANOVA and ANN Analysis". Journal of Materials Processing Technology, volume 209 (1), pages 225–232, 2009.
- [6] K. Prasad and K. Jayadevan. "Simulation of Stirring in Stir Casting". Procedia Technol, volume 24, pages 356-363, 2016.
- [7] P. Ross. "Taguchi Techniques for Quality Engineering: Loss Function, Orthogonal Experiments, Parameter and Tolerance Design". McGraw-Hill. ISBN 978-0442237295, 1996.
- [8] R. Singh, R. Singh, and J. Dureja, I. Farina, F. Fabbrocino. "Investigations for Dimensional Accuracy of Al Alloy/Al-MMC Developed by Combining Stir Casting and ABS Replica Based Investment Casting". Composites Part B: Engineering, volume 115, pages 203–208, 2017.
- [9] A. Satpathy, S. Tripathy, N. Senapati, and M. Brahma. "Optimization of EDM Process Parameters for Al-SiC-20% SiC Reinforced Metal Matrix Composite with Multi Response Using TOPSIS". Materials Today: Proceedings, volume 4 (2), pages 3043–3052, 2017.
- [10] K. Hamim, S. Akbari, S. Fakhrhoseini, H. Khayyam, A. Pakseresht, E. Ghasali, M. Zabet, and K. Munir. Ji. "Carbon Fiber Reinforced Metal

## International Journal of Research in Advent Technology, Vol.6, No.12, December 2018 E-ISSN: 2321-9637

Available online at www.ijrat.org

Matrix Composites: Fabrication Processes and Properties". Composites Part A: Applied Science and Manufacturing, volume 92, pages 70–96, 2017.

- [11] A. Gore and N. Patil. "Wire Electro Discharge Machining of Metal Matrix Composites: A Review". Procedia Manufacturing, volume 20, pages 41–52, 2018.
- [12] R. Garg and H. Singh. "Optimisation of Process Parameters for Gap Current in Wire Electrical Discharge Machining". International Journal of Manufacturing Technology and Management, volume 25, page 161, 2012.
- [13] A. Roy, and K. Kumar. "Effect and Optimization of Various Machine Process Parameters on the Surface Roughnes in EDM for an EN19 Material using Response Surface Methodology". Procedia Mater. Sci., volume 5, pages 1702-1709, 2014.
- [14] J. Mathai, J. Tony, and S. Marikkannan. "Processing, Microstructure and Mechanical Properties of Al2O3 and SiC Reinforced Magnesium Metal Matrix Hybrid Composites". Materials Today, volume 4 (6), pages 6750–67, 56, 2017.